

KING COUNTY

SITE ID:	Phillips 66 Renton Terminal		Cleanup Site ID: 29		FS ID: 2070
Alternate Name(s):		BP RENTON TERMINAL, ConocoPhillips Renton Terminal, Phillips 66 Renton Terminal, TOSCO NORTHWEST CO RENTON TERMINAL, TOSCO NW CO, TOSCO RENTON TERMINAL			
LOCATION:		WRIA: 9	Lat/Long: 47.460 -122.224		View Vicinity Map
Address:	2423 LIND AVE SW RENTON 98055	Township 23N	Range 5E	Section 19	Legislative District: 11 Congressional District: 9
STATUS:	Cleanup Started	Rank: 5	View Site Web Page		View Site Documents
Responsible Unit: Northwest		Site Manager: Cruz, Jerome		Statute: WPCA - Ch. 90.48	
Is Brownfield?		Has Environmental Covenant?		Is PSI Site?	
NFA Received?		NFA Date:		NFA Reason:	

ASSOCIATED CLEANUP UNIT(s)

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
957	Phillips 66 Renton Terminal	Upland	Ecology-supervised or conducted	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	10/1/1990	2/1/1991		Ecology	Sato, Brian
CleanupSite		Hazardous Sites Listing/NPL			2/15/1991			Sato, Brian
CleanupSite		Order/Decree/Amendment		8/5/2010				Northwest Region
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasibility Study	Completed	11/5/2010	1/9/2013	Agreed Order	PLP	Cruz, Jerome
CleanupSite MilestoneTyp		Ecology Post-Cleanup O & M	Canceled	7/1/1988	6/30/1997		Ecology	Sato, Brian
Upland		Ind - Report Received			5/1/2013			
Upland		Ind - Report Received			5/1/2013			
Upland		Ind - Report Received			5/1/2013			
Upland		Ind - Report Received			5/1/2013			
VcpProject	NW1259	VCP Application	Completed	5/20/2004				
VcpProject	NW1259	VCP Termination	Completed		4/9/2008			Olsen, Russ
VcpProject	NW1259	VCP Opinion on Interim Action	Completed					Peck, Norm
VcpProject	NW1259	VCP Opinion on Cleanup Action Plan	Completed		9/28/2007			Peck, Norm

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C	C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014